

## **Radiation Safety Training and Radiation Monitoring Badges**

Participants in the laboratory exercises and/or the certification examination process must possess both *Radiation Safety Training and Radiation Monitoring Badges* prior to utilizing the nuclear moisture-density gauges.

***Students must bring a copy of their Radiation Safety Training Certificate and their radiation monitoring badge to the class.***

Radiation Safety Training is normally provided by the various gauge manufacturers (e.g. – Troxler, CPN, Humboldt).

Information, schedules and registration for these classes may be obtained by contacting Troxler at: 877-876-9537 or visiting their website [www.troxlerlabs.com](http://www.troxlerlabs.com)

***Repeat – Students must bring a copy of their Radiation Safety Training Certificate and their radiation monitoring badge to the class.***

***Students without the Radiation Safety Training and Radiation Monitoring Badge WILL NOT BE ABLE TO DO THE LAB PORTION OF THE APAO DENSITY CLASS OR TAKE THE ODOT PRACTICAL TEST FOR CERTIFICATION. (This means “you can not be Certified in Density”)***